

ENECON Italia Solves Cavitation Problems For Ferry Boat Operator

Cavitation problems
on a ferryboat's
salt-water discharger
repaired and
protected from
future attack with
DuraTough DP & DL



Severe cavitation damage clearly evident on discharger after grit blasting/cleaning.

DuraTough Primer applied to the prepared surface.



DuraTough DP applied to re-build damaged surface.



DuraTough DL applied to completely seal and protect the discharger.

ENECON Ibérica · C/ St. Gervasi de Cassoles, 96-98 entlo. 3ª · 08022 Barcelona
· Telf: 93 211.15.30 · Fax: 93.253.11.31
Website: www.proenecon.com · Email: eneconib@proenecon.com