


CHEMCLAD XC Solves On-Going Corrosion Problems in Sulfuric Acid Loading Area at Australian Nickel Mine



The maintenance engineers at this Laterite Nickel Mine in Western Australia had a very severe corrosion problem in this concrete loading bay. Trucks load and unload chemicals in this area 7 days a week.

Various high-build coatings and patching materials were tried over the years with very poor results. The engineers turned to the ENECON Australia Industrial Solutions Team for help. They recommended CHEMCLAD XC, ENECON's finest chemical protection system, be used to completely seal the entire loading bay with outstanding results.