


Major Hospital Center
in Houston, Texas,
Turns to ENECLAD FPS
To Waterproof & Protect
Large Mechanical
Equipment Room



This large cancer center located in Houston was experiencing serious leak problems in their mechanical room located on the second floor.

The facilities engineers needed a cost effective, long-term solution utilizing state-of-the-art materials. They turned to the ENECON Engineering Team for help.

ENECRETE DuraQuartz was used to repair all the cracks in the floor followed by a one-coat application of **ENECLAD FPS** to seal and protect the entire 15,000 square foot floor area.