


## Wastewater Treatment Facility Located in the Pacific Northwest



## Protects Digester Roof Insulation With ENESEAL HR

Brien Neill, ENECON's Vice President for Western Operations, provided the following report:

“Over the years, the insulation on the plant's digesters had been compromised in a number of areas and was becoming saturated with water. As a result, it was deteriorating at an accelerated rate and was diminishing the efficiency of their operating unit. If a solution was not provided, the insulation would have continued to deteriorate and would have eventually needed to be replaced – a

very costly procedure, as you can imagine.

Consequently, the plant's Wastewater Treatment Supervisor elected to take a 'proactive' preventive maintenance approach and utilize ENESEAL HR to protect the insulation – *at a fraction of the cost of replacing the insulation if it had been allowed to continue to deteriorate.*

The on-site staff of the wastewater treatment plant applied the ENESEAL themselves and are extremely satisfied with it's performance.”



ENECON Ibérica · C/ St. Gervasi de Cassoles, 96-98 entlo. 3ª · 08022 Barcelona  
·Telf: 93 211.15.30 · Fax: 93.253.11.31  
Website: [www.proenecon.com](http://www.proenecon.com) · Email: [eneconib@proenecon.com](mailto:eneconib@proenecon.com)