


Ship's Propellers Repaired and Protected with CeramAlloy in the Philippines



The accompanying photographs illustrate a very successful application carried out at a shipyard in

the Philippines. METALCLAD CeramAlloy CP+ and CL+ were used to completely repair

and then protect the two propellers on this large container ship. Two years later divers inspected the

CeramAlloy system and advised that it was in absolutely perfect condition.



ENECON Ibérica · C/ St. Gervasi de Cassoles, 96-98 entlo. 3ª · 08022 Barcelona
· Telf: 93 211.15.30 · Fax: 93.253.11.31
Website: www.proenecon.com · Email: eneconib@proenecon.com